



# ENGINEERING CHANGE NOTE:

ECN #: 1049

**ASSEMBLY:** BIOS101B

**NEW ASSEMBLY:** BIOS101B

**CURRENT REV:** G

**NEW REV:** H

**DESCRIPTION:** SX-20 LTC output mod

**DATE:** 09/04/2008

**REASON FOR CHANGE:**

- Safety Issue
- Bug Fix
- Reliability Reasons
- UL Compliance Issue
- EMC Compliance Issue
- Software Change
- New Feature
- Quality Issue
- Cosmetic Change
- Cost Reduction

Inprove LTC output

**COMPATIBILITY MAINTAINED:** Yes

**DETAILS OF CHANGE:**

Replace C17 10n, with 100n 0402 capacitor

Label as Rev H

NOTE TO SUBCONTRACTORS: Implement this ECN from the next manufacturing batch, and ALL work in progress

NOTE TO PRODUCTION: Implement this ECN on ALL work in progress

**SIGNATURES:**

**Engineer:**

**Implementor:**

**Date:**

**Operations Manager:**